

SoEMT

1	2			
2	3			
3	3			
4	3			
1	3			

Active

Inactive

Active

Inactive

Active

SMT

1	2			
3	3			
1	2			
3	3			
1	2			

Fig. 1B
(Prior Art)

Fig. 1A
(Prior Art)




Fig. 2




Fig. 3




Fig. 4




Figure 5